4 BRS 5 BRS 6 BRS 7 BRS						3 BRS	2 BRS	1 BRS	Туре
***************************************	2	7	2	24	28	152	0	29	Hits
	(pavement with manag\$) and repair\$ and computer\$	5447336.URPN.	5447336.pn.	pavement adj management	<pre>pavement and management and computer and (repair rehabilitat\$)</pre>	pavement and management and computer	pavement adj management adj primer	3873225.URPN.	Search Text
USPAT; US-PGPUB;	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT; US-PGPUB; 2003/03/26 EPO; JPO; DERWENT; IBM_TDB 09:49	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT	DBs
2003/03/26	PUB; 2003/03/25 _TDB	2003/03/25 14:51	2003/03/25 14:49	РИВ; <mark>2003/03/25</mark> _TDB	PUB; 2003/03/25 _TDB	2003/03/26 09:49	S-PGPUB; 2003/03/25 ; IBM_TDB	2003/03/22 18:41	Time Stamp
									Comments
Truncation	Truncation overflow.								Error Definition

 $'' \in \mathfrak{R}_{i}$

.

ω	7	6	<u> </u>	44	Tω	N		
							'	
BRS	BRS	BRS	BRS	BRS	BRS	BRS	BRS	Туре
L10	F9	L8	L7	16	L5	L4	L3	۲ #
Ŋ	3 O	P	ω	7	12	16	Н	Hits
5752783.URPN.	("3259034" "3638540" "4379653" "4818139" "5044820" "5164641" "5248216" "5333966" "53345471" "5362177" "5362177" "5484227"	5752783.pn.	("4700223" "5075772" "5323647" "5517419"	5721685.URPN	5549412.URPN	("3259034" "3675545" "3879149" "5044820" "5288166" "5299130" "5333966" "5356238"	5549412.pn.	ro
T .	"3604512" "3846035" "4761037" "5015120" "5044819" "5052854" "5177415" "5328295" "5333969" "5333969" "53362176" "53457394" "5549412").		"4899296" "5214757" "5364205" "5549412").	И.	Ν.	"3604512" "3846035" "4473319" "5119102" "5288167" "5328295" "5337243" "53362177").		Search Text
USPAT	USPAT	USPAT	USPAT	USPAT	USPAT	USPAT	USPAT	
AT	· AT	_		_				DBs
2003/03/26 09:48	, 2003/03/26 09:47	2003/03/26 09:47	2003/03/26 09:45	2003/03/26 09:44	2003/03/26 09:42	2003/03/26 09:40	2003/03/26 09:47	Time Stamp
								Comment
								Error Definition
0	0	0	0	0	0	0	0	rs ro

	Туре	Ľ #	Type L # Hits	Search Text	DBs	Time Stamp	Comment	Error Definition	RS O H
9	BRS	L11	45	pavement and computer	EPO; JPO; DERWENT; 09 IBM_TDB	2003/03/26			0